



C8983699832 REPLACEMENT TRANSMISSION MOUNT MT FOR ISUZU DMAX 4X4

Our Product Introduction

Basic Information

- Place of Origin: CHINA
- Brand Name: HOSEM
- Model Number: C8983699832
- Minimum Order Quantity: 50PCS
- Packaging Details: Hosem Brand/Neutral/Customized for customer needs
- Delivery Time: 5-10 work days
- Payment Terms: T/T, L/C, Western Union, Alipay



HAOSH

Email: info@gzhaosh.com

Product Specification

- OEM NO.: C8983699832 8983699832
- Part Name: TRANSMISSION MOUNT
- Apply: Manual Transmission
- Car Model: FOR ISUZU DMAX 4X4
- Engine Type: Diesel
- Highlight: ISUZU DMAX TRANSMISSION MOUNT,
4X4 TRANSMISSION MOUNT,
REPLACEMENT TRANSMISSION MOUNT



HAOSH

Email: info@gzhaosh.com

Product Description

REPLACEMENT TRANSMISSION MOUNT MT FOR ISUZU DMAX 4X4 C8983699832 8983699832

Product Name	TRANSMISSION MOUNT
Car Fitment	Isuzu DMAX 4X4
Part Number	C8983699832 8983699832
Price	Negotiable,the more the quantity, the lower the price
Packaging	Hosem Brand/Neutral/Customized for customer needs
Shipment	By Sea/ Air/ Express
Deliver Date	5-10days After receiving the deposit
Quality Guarantee	3-6months

Company Advantages

1. We have profession knowledge about Isuzu spare parts ,more than 15 years experience in chassis parts and engine parts etc.
2. We can offer genuine parts, oem, genuine made in china parts to you.
- 3.All parts can check with part number,all parts can order follow part number.
4. Quick delivery time,will delivery the goods within 15 days.
5. Safe packing to protect the goods, such as wooden box, Iron sheet for our parts.
- 6.We can make custom labels and packaging for customers.
7. Small quantity can accept.

**HAOSH***Email:info@gzhaosh.com*

FACTORY



WAREHOUSE



SHOWROOM



HOT SELL PRODUCT

THERMOSTAT



WASHER PUMP



WASHER TANK MOTOR



BALL JOINT



CONNECTING ROD



POWER STEERING PUMP



ALTERNATOR REGULATOR



RADIATOR CAP



VACUUM PUMP FEED OIL PIPE




SHIPPING



How often to replace the transmission mount ?

- 1.If left in working order for long periods of time, deterioration is accelerated and may need to be inspected and considered for replacement every 3 - 4 years or 40 - 60,000 kilometres.
- 2.Frequently loaded or towed vehicles, the pressure on the gearbox is large, and the force transferred to the bracket pad is also large, which will make the bracket pad deformed more quickly.

 **HAO SHENG** Guangzhou Haosheng Supply Chain Co., Ltd

 86-18024581436

 hshauto@gzhaosh.com

 isuzuautospareparts.com

Guangzhou Baiyun District Jiaoteng Street Yueqiang Creative Park 3 Building 201