8-97329780-0 897329780 Frt Crankshaft Oil Seal 109*137*13 FOR ISUZU 700P 4HK1 4HF1

HAO SHENG

Basic Information

- Place of Origin:
- Brand Name:
- China OEM
- Model Number: ISUZU 700P 4HK1 4HF1
- Minimum Order Quantity:
- Packaging Details:
- Delivery Time:
- Payment Terms:
- Supply Ability:

ty:	1pcs
	Neutral packing
	10-15days
	L/C, T/T, Western Union
	100,000,000/months



HAOSH Email:info@gzhaosh.com

ISUZU

Product Specification

- Part Name:
- Part Number:
- Model:
- Quality:
- Moq:
- Warranty:
- Packing:
- Color:
- Highlight:

More Images

Frt Crankshaft Oil Seal 8-97329780-0 897329780 700P 4HK1 4HF1

High

10 Pcs

- 6 Months
- Neutral Packing Or OEM Packing
- As Picture Shows
 - 897329780 Crankshaft Oil Seal, 897329780 Crankshaft Oil Seal, 4HK1 Crankshaft Oil Seal



HAOSH Email:info@gzhaosh.com

Our Product Introduction



HAOSH

Product Description

HADSHENS



HAOSH Emilioferational Frt Crankshaft Oil Seal 109*137*13 FOR ISUZU 700P 4HK1 4HF1 8-97329780-0 897329780







Certificates and factories



ISUZU TRUCK	NPR	NQR	NKR
IDOLO THOUR	NMR	NLR	ELF
- Damen	Vc46	FVR	FTR
	CYZ	CXZ	EXZ
- P	JMC	KY	
Contraction of the second seco	N800	N900	N720
	N725		
ISUZU PICKUP	DMAX 02-04	DMAX 06-11	DMAX 12
115	LT	RM	MUX
	TFR		
TRANSIT	TRANSIT	V348 2.2	V348 2.4
A	V362	U375	

Our advantages

1.We specialize in Japanese auto parts

2.High-Quality goods, Aftermarket quality & OEM quality

3.No MOQ requipments Short Delivey time

4.Short Delivey time

Products range

1.Engine Parts : Thermostat ,Auto Cylinder , Starter Motor , Pump , Engine Mount , Injetor Pump Valve , Engine Pipe , Timing , Caps, Pulley , Turbocharger ;

2.Chassis Parts : Steering System , Shock Absorber , Suspension , Ball Joint , Drive Shaft , Auto Tank , Differencial Parts , Auto Cable , Wheel Hub ;

3.Electrical System : Ignition system ,ABS Speed Sensor ,Auto Switch ,Relay ;

4.Brake System & Clutch System & Booster

5.Cooling System : Fan Clutch , Radiator , A/C , Fan Blade ;

6.Engine Gasket Set & Repair Kits;

7. Belt & Bushing & Bearing & Oil Seal ;

8.Body Exterior: Lamps , Fender , Bumper , Grille , Mirror ;

8-97329780-0 Crankshaft front oil seal For ISUZU 700P/4HK1/4HF1 models. It can effectively prevent engine oil leakage and ensure that the oil in the crankcase is in normal working condition. Keeping the oil sufficient and clean provides good lubrication conditions for normal engine operation. For example, when the vehicle is running at high speed, the oil seal can withstand great pressure and stop the oil from seeping out. This not only reduces oil loss, but also avoids wear and tear on the engine caused by insufficient oil, safeguarding engine performance and life.

HAD SHENG Guangzhou Haosheng Supply Chain Co., Ltd

🔇 86-18024581436 🖸 hshauto@gzhaosh.com 🙆 isuzuautospareparts.com

Guangzhou Baiyun District Jiaoteng Street Yueqiang Creative Park 3 Building 201