Basic Information

. Place of Origin: China 100PCS Minimum Order Quantity:

 Packaging Details: Nylon Bag/Neutral/Customized for customer

• Delivery Time: 10-15days After receiving the deposit

• Payment Terms: L/C, T/T, Western Union





HAOSH Email:info@g

Product Specification

• Part Name: **CENTER BEARING**

• OE Number: MC802792

· Car Model: For MITSUBISHI FUSO

• Condition: New

• Highlight: MITSUBISHI FUSO CENTER BEARING,

MC802792 CENTER BEARING





HAOSH Email:info@a

Product Description

CENTER BEARING MC802792 FOR MITSUBISHI FUSO

Product Name	CENTER BEARING
Car Fitment	FOR MITSUBISHI FUSO
Part Number	MC802792
Size	Standard
Packaging	Nylon Bag/Neutral/Customized for customer needs
Shipment	By Sea/ Air/ Express
Deliver Date	10-15days After receiving the deposit
Price	Negotiable

How to Check if the center bearing is Damaged?

Check for Cracks and Tears:Carefully examine the drive shaft mounting bushing for any visible cracks, tears or splits in the rubber material. These are common signs of wear and damage. Pay close attention to the areas where the bushing connects to the drive shaft and the vehicle's frame or other mounting points.

















 $\label{thm:condition} \textbf{Guangzhou Hao Sheng Supply Chain Co.,} \textbf{LTD recommends more accessories:}$













HAOSH

HAOSH

HAOSH













HAOSH

HAOSH

HAOSH

HAD 5HENG Guangzhou Haosheng Supply Chain Co., Ltd



86-18024581436



hshauto@gzhaosh.com



isuzuautospareparts.com

Guangzhou Baiyun District Jiaoteng Street Yueqiang Creative Park 3 Building 201